VOYAGER OF THE SEAS 1/25/2004

DETAILS OF INSPECTION VIOLATIONS

NO. LOCATION DESCRIPTION		REF.	POINTS	CRITICAL				
1 ISLAND GRIL	L	33	0	No				
LOOSE BULKHEAD PANELS WERE NOTED ON THE PORT AND STARBOARD SIDE OF THE HOT GRILL LINES.								
This item was re	This item was rectified by our facilities management and a record AVO was made.							
2 WINDJAMME	R BUFFET LINES	33	0	No				
THE STAINLESS STE	EL PANEL AT THE BASE OF THE BUFFET CABINETRY WAS LOOS	SE.						
This item was re	ctified by our facilities management and a record AV	O was	made.					
3 WINDJAMME	R STARBOARD BUFFET LINE	21	1	No				
THE COUNTER WAS	ROUGH BETWEEN THE BAIN MARIE STATIONS AND THE INDUCT	TION WC	K.					
This item is sch	eduled to be rectified in the up coming Dry Dock N	lay 2 nd	2004.					
4 CASINO PA	NTRY 33 0 No							
THE ALTERNATE EN	TRANCE INTO THE CASINO PANTRY WAS DAMAGED AT THE JUN	ICTURE	BETWEEN TH	HE BULKHEAD AND DECK.				
This item was re	ctified by our facilities management and a record AV	O was	made.					
5 JOHNNY R	OCKETS GRILL 33 0 No							
A LOOSE BULKHEAD	PANEL WAS NOTED ON THE LEFT SIDE OF THE HOT GRILL.							
This item was re	ctified by our facilities management and a record AV	O was	made.					
6JOHNNY ROCKETS	GRILL	21	1	No				
GAPS WERE NOTED	IN THE GRILL DRIP PAN HOUSING THAT MADE CLEANING DIFFIC	CULT.						
This item was re	ctified by our facilities management and a record AV	O was	made.					
7 WINDJAMME	R SALAD BUFFET	36	0	No				
ENSURE THAT THE I	LIGHTING IN THIS AREA CAN BE RAISED TO 220 LUX WHEN CLEA	NING TA	AKES PLACE.					
The lighting doe	s reach the 220 lux requirement once the system is to	urned o	on for the o	leaning process.				
8 MAIN GALLE	Y - DECK 5	38	0	No				
A MOP WAS NOTED IN THE CLEANING STORAGE ROOM STORED IN A MOP BUCKET. THIS DID NOT ALLOW THE MOP TO AIR DRY.								
This has been corrected staff was coached regarding the storage of mops; this will be monitored on an ongoing bases.								
9 MAIN GALLE	Y - DECK 5	26	0	Yes				
SEVERAL PLATES W	ERE NOTED IN THE BELL BOX SOILED AND STORED AS CLEAN.							
All staff has been	coached of the correct way to stow clean plates, continu	ous mo	nitoring wi	ll ensure compliance.				
10 MAIN GALLE	7 - DECK 5	21	1	No				
THE LID ON THE SOI	DA MACHINE WAS CRACKED, MAKING IT DIFFICULT TO CLEAN.							
A new lid has be	en ordered from Coca Cola company, we are awaiting	g deliv	ery					
11 STAFF MESS	PANTRY	15	5	Yes				
A HALF-GALLON OF MILK WAS FOUND IN A REFRIGERATOR FROM ISLAND DAIRIES IN JAMAICA. THIS MILK WAS NOT LABELED AS GRADE								
This write up has	s been re-classed and taken care of.							
12 MAIN GALLE	7 - DECK 4	20	2	No				
SIX SPOONS WERE NOTED IN THE POTASH AREA WITH DAMAGED HANDLES, MAKING THEM DIFFICULT TO CLEAN.								

These utensils have been discarded.
VOYAGER OF THE SEAS 1/25/2004

DETAILS OF INSPECTION VIOLATIONS

NO. LOCATION REF. POINTS **CRITICAL DESCRIPTION** 13 **MAIN GALLEY - DECK 4** 0 No THE POTASH MACHINE WAS POSTED OUT OF ORDER. THE THREE COMPARTMENT SINK WAS BEING UTILIZED TO COMPENSATE FOR THIS Correct processes were being followed. **MAIN GALLEY - DECK 4** 21 1 No PEELING SEALANT WAS NOTED IN THE VENTILATION HOOD OVER THE DOUGHNUT FRYER IN THE BAKERY. The facilities management has an ongoing program to replace pealing sealant throughout the galleys record AVO was made. 15 MAIN GALLEY - DECK 4 33 0 No A HOLE WAS NOTED IN THE BULKHEAD NEXT TO THE DOUGHNUT FRYER IN THE BAKERY. This item was rectified by our facilities management and a record AVO was made. **MAIN GALLEY - DECK 3** A CRATE OF MILK (NINE HALF GALLON CONTAINERS) WAS NOTED IN THE SOUP AND VEGETABLE WALK-IN REFRIGERATOR FROM ISLAND DAIRIES IN JAMAICA. THIS MILK WAS NOT LABELED AS GRADE A. This write up has been re-classed and taken care of. Page 1 of 2DRAFT COPY DRAFT COPY **MAIN GALLEY - DECK 3** 16 0 Yes CHEESE PLATES WERE NOTED IN REFRIGERATOR R-03-38. AN INTERNAL TEMPERATURE OF THE CAMEMBERT CHEESE ON TWO OF THE PLATES WAS TAKEN AND FOUND TO BE 45°F. IT WAS STATED BY THE STAFF THAT THE PLATES WERE PREPARED THE NIGHT BEFORE THE INSPECTION. THE CHEESE WAS DISCARDED IMMEDIATELY. The cheese was discarded immediately, the pantry-men were coached on the importance of refrigeration. **MAIN GALLEY - DECK 3** 20 2 No THE THERMOMETER IN REFRIGERATOR R-03-38 MENTIONED IN THE PREVIOUS ITEM WAS READING 48°F. The thermometer was discarded immediately and a new one put in its place. **DINING ROOMS** No THE FINISH ON THE WAIT STATIONS WAS CHIPPED. LEAVING EXPOSED WOOD THAT WAS DIFFICULT TO CLEAN. This item is scheduled to be replaced in our up coming Dry Dock May 2nd 2004. **CREW GALLEY** CONDENSATE WAS NOTED IN THE VENTILATION HOOD OVER THE COMBI-OVENS. THIS CONDENSATE WAS DRIPPING ONTO THE DECK BELOW. This item was rectified by our facilities management and a record AVO was made.

The staff at the crew galley has been coached on the importance of correct storage of clean and dirty silver.

26

Yes

CREW GALLEY

ONE KNIFE WAS SOILED AND STORED AS CLEAN IN THE PANTRY.

VOYAGER OF THE SEAS 1/25/2004

DETAILS OF INSPECTION VIOLATIONS

	LOCATION SCRIPTION	REF.	POINTS	CRITICAL	
22	CREW GALLEY	38	0	No	
A SIG	ON WAS MISSING ON THE CLEANING LOCKER.				
Thi	s item was rectified immediately.				
23	PROVISIONS - VEGETABLE UNPACKING ROOM	21	1	No	
HOLE	S WERE NOTED ON THE COMBI-OVEN WHERE A KNOB WAS MISSING.				
Thi	s unit will be removed from the area in Dry-Dock				
24	PROVISIONS - VEGETABLE UNPACKING ROOM	08	0	No	
	FAUCET AT THE SINK IN THE CLEANING LOCKER HAD A THREADED HOSE NOT LOCATED ON THE WATER LINES SUPPLYING THE SINK.	BIB CONNEC	TION. A BAC	KFLOW PREVENTION	ON DEVIC
With	the coordination of the facility Division this will be corrected	ed AVO was	made.		
25	PROVISIONS - FRUIT WALK-IN	33	0	No	
A LA	RGE GAP WAS NOTED NEAR THE DECK WHERE THE PROFILE STRIP HAD	PULLED AWA	Y FROM THE	BULKHEAD.	
This	item is scheduled to be rectified in our up coming Dry Dock Ma	ay 2 nd 2004.			
26	POOL BAR PANTRY	20	2	No	
	SPOON WITH A DAMAGED HANDLE AND ONE KNIFE WITH A DAMAGED BL II DIFFICULT TO CLEAN.	ADE WERE FO	OUND IN THE	WAREWASH AREA	, MAKING
The	se utensils have been discarded.				
27	POOL BAR PANTRY	21	1	No	
THE SOIL	COOLER USED TO HOLD PINA COLADA MIX WAS CRACKED, EXPOSING THED.	HE INSULATIO	N. THE INSU	LATION WAS WET	AND
Thi	s container has been discarded.				
28	CORRECTIVE ACTION STATEMENT	*	0	No	
	EVELOPING THE CORRECTIVE ACTION STATEMENT FOR THIS INSPECTION OF INTERPRETATION OF THE COLUMN (WORTH 3 - 5 POINTS), WHETHER DEBITED OR NOT				D WITH

PROCEDURES AND MONITORING PROCEDURES IMPLEMENTED TO PREVENT THE RECURRENCE OF THE CRITICAL DEFICIENCY.

PREPARE CORRECTIVE ACTION STATEMENT AS A WORD PROCESSING OR SPREADSHEET FILE WHICH WILL BE SENT TO USPHS / VSP AS AN EMAIL MESSAGE ATTACHMENT. PLEASE EMAIL CORRECTIVE ACTION STATEMENT TO: VSP@CDC.GOV

USE EMAIL MESSAGE SUBJECT LINE: VOYAGER OF THE SEAS - CAS - 1/25/2004